

**WASTEWATER DEPARTMENT STATUS REPORT
APRIL 2022
COUNCIL DISTRICT NO. 3
QSCEND**

| COUNCIL DISTRICT | ADDRESS | REQUIRED ACTION | STATUS | QSCEND ENTRY DATE BY WASTEWATER PERSONNEL | COMPLETION DATE |
|------------------|-----------------|--------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|-------------------------------------------|-----------------|
| 3 | 3509 Lake Trail | The City's gravity sewer lateral line needs to be repaired at 95 linear feet from the 6-inch cleanout. | Open/In progress | 4/25/2022 | |
| 3 | 4005 Arkansas | Manhole No. 02113003 needs to be repaired. | Open/In progress | 4/22/2022 | |
| 3 | 3510 Colorado | Manhole No. 02103006 needs to be repaired. | Open/In progress | 4/7/2022 | |
| 3 | 32 Antigua | The 6-inch cleanout stand pipe needs to be repaired. | Open/In progress | 4/6/2022 | |
| 3 | 3917 California | The City's gravity sewer service line needs to be repaired due to damage from the installation of a fiber optic line. | Open/In progress | 4/5/2022 | |
| 3 | 1901 36th St | Manhole No. 02102002 needs to be repaired. | Open/In progress | 3/2/2022 | |
| 3 | 21 Earnest | The City's gravity sewer service line needs to be repaired at 1.7 linear feet from the 6-inch cleanout, where the pipe has dropped at an offset joint. | Open/In progress | 1/31/2022 | |
| 3 | 3540 Martinique | The sink hole near the 6-inch cleanout needs to be dye tested. | Open/In progress | 11/16/2021 | |
| 3 | 4125 Lake Trail | The sewer manhole needs to be repaired by cementitious lining. | Open/In progress | 10/5/2021 | |
| 3 | 4309 Idaho | The City's gravity sewer service line needs to be repaired at 2 linear feet from the 6-inch cleanout due to pipe separation. | Closed | 3/14/2022 | 4/24/2022 |

**WASTEWATER DEPARTMENT STATUS REPORT
 APRIL 2022
 COUNCIL DISTRICT NO. 3
 QSCEND**

| COUNCIL DISTRICT | ADDRESS | REQUIRED ACTION | STATUS | QSCEND ENTRY DATE BY WASTEWATER PERSONNEL | COMPLETION DATE |
|------------------|-----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|-------------------------------------------|-----------------|
| 3 | 4005 Arkansas | The sidewalk around Manhole No. 02113003 needs to be dye tested. Dye was observed entering the side walls. | Closed | 3/17/2022 | 4/20/2022 |
| 3 | 3645 Williams | The City's gravity sewer main line needs to be televised to locate the service connection. The camera broke when starting the televising on 03/27/2022, and was sent to the repair shop. The plumber for the site located the service connection on 03/28/2022. | Closed | 3/21/2022 | 3/28/2022 |
| 3 | 3509 Lake Trail | The City's gravity sewer service line needs to be televised to check the condition. The line was packed with grease. The top of the pipe was damaged by a fiber optic line at 9.3 linear feet fro the 6-inch cleanout. | Closed | 4/14/2022 | 4/18/2022 |
| 3 | 4109 Indiana | The City's gravity sewer main line needs to be televised to locate the service connection. No defects were observed. A new 6-inch cleanout cap was installed. | Closed | 4/19/2022 | 4/21/2022 |